



REVISED SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service
Washington, DC

U.S. Department
of Transportation

**Federal Aviation
Administration**

CE-03-02R1
March 24, 2005

<http://www.faa.gov/aircraft/safety/alerts/>

This is information only. Recommendations aren't mandatory.

Background

We have cancelled SAIB CE-03-02 due to the certification of the Leading Edge Exhaust Systems, LLC replacement exhaust system on the 150, 160, and 180 horsepower engines installed on **The New Piper, Inc. model PA-18 aircraft.**

For Further Information, Contact

David Swartz, Aerospace Engineer, FAA
Anchorage ACO, ACE-115N, 222 W. 7th Ave.,
#14, Room 128, Anchorage, AK 99513-7587;
phone: (907) 271-2671; fax: (907) 271-6365;
email: dave.swartz@faa.gov

For a copy of SAIB CE-03-02, visit our
website at

<http://www.faa.gov/aircraft/safety/alerts/>